WORK INSTRUCTION

Document ID: DOC-0000921
Project: PRJ-001
Uploaded on: 2024-02-01
Uploaded by: user050
Export class: EAR99

Assembly of P-100273 at plant PLT02

Part Number: P-100273
Revision: A.1
Plant: PLT02
Station: ST-63
Torque (Nm): 20
Cycle time (s): 152

Step 1: Inspect incoming part

Step 2: Record result

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Move to next station

Assembly of P-100981 at plant PLT01

Part Number: P-100981
Revision: A.1
Plant: PLT01
Station: ST-78
Torque (Nm): 20
Cycle time (s): 249

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Visual check

Step 4: Torque to specification

Step 5: Move to next station