# WORK INSTRUCTION

**Document ID:** DOC-0001784
**Project:** PRJ-036
**Uploaded on:** 2025-03-03
**Uploaded by:** user021
**Export class:** EAR99

## Assembly of P-100893 at plant PLT04

**Part Number:** P-100893
**Revision:** B.1
**Plant:** PLT04
**Station:** ST-67
**Torque (Nm):** 20
**Cycle time (s):** 116

Step 1: Apply thread locker

Step 2: Fit fasteners

Step 3: Torque to specification

Step 4: Visual check

Step 5: Record result

Step 6: Visual check

Step 7: Inspect incoming part

## Assembly of P-100999 at plant PLT04

**Part Number:** P-100999
**Revision:** A.1
**Plant:** PLT04
**Station:** ST-55
**Torque (Nm):** 12
**Cycle time (s):** 250

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Apply thread locker

Step 4: Inspect incoming part

Step 5: Inspect incoming part