WORK INSTRUCTION

Document ID: DOC-0001801
Project: PRJ-005
Uploaded on: 2025-03-10
Uploaded by: user132
Export class: EAR99

Assembly of P-100277 at plant PLT04

Part Number: P-100277
Revision: B.1
Plant: PLT04
Station: ST-84
Torque (Nm): 5
Cycle time (s): 175

Step 1: Clean mating surface

Step 2: Record result

Step 3: Torque to specification

Step 4: Visual check

Step 5: Apply thread locker