EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001807
Project: PRJ-007
Uploaded on: 2025-03-12
Uploaded by: user018
Export class: ECCN-3A001

Assembly of P-100760 at plant PLT04

Part Number: P-100760
Revision: A.1
Plant: PLT04
Station: ST-26
Torque (Nm): 5
Cycle time (s): 61

Step 1: Visual check

Step 2: Visual check

Step 3: Record result

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Inspect incoming part

Step 7: Torque to specification

Assembly of P-100265 at plant PLT03

Part Number: P-100265
Revision: A.1
Plant: PLT03
Station: ST-77
Torque (Nm): 20
Cycle time (s): 107

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Apply thread locker

Step 4: Visual check

Step 5: Inspect incoming part