WORK INSTRUCTION

Document ID: DOC-0002354
Project: PRJ-014
Uploaded on: 2025-12-01
Uploaded by: user053
Export class: EAR99

Assembly of P-103012 at plant PLT04

Part Number: P-103012
Revision: A.1
Plant: PLT04
Station: ST-67
Torque (Nm): 5
Cycle time (s): 139

Step 1: Move to next station

Step 2: Apply thread locker

Step 3: Record result

Step 4: Visual check

Step 5: Fit fasteners

Step 6: Torque to specification

Step 7: Record result

Step 8: Visual check