WORK INSTRUCTION

Document ID: DOC-0002079
Project: PRJ-012
Uploaded on: 2025-07-16
Uploaded by: user098
Export class: EAR99

Assembly of P-101278 at plant PLT01

Part Number: P-101278
Revision: B.1
Plant: PLT01
Station: ST-65
Torque (Nm): 2.5
Cycle time (s): 32

Step 1: Clean mating surface

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Inspect incoming part

Step 5: Inspect incoming part