WORK INSTRUCTION

Document ID: DOC-0000826
Project: PRJ-036
Uploaded on: 2023-12-05
Uploaded by: user026
Export class: EAR99

Assembly of P-100431 at plant PLT03

Part Number: P-100431
Revision: A.1
Plant: PLT03
Station: ST-78
Torque (Nm): 2.5
Cycle time (s): 123

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Fit fasteners

Step 4: Inspect incoming part

Step 5: Fit fasteners

Assembly of P-100399 at plant PLT04

Part Number: P-100399
Revision: B.1
Plant: PLT04
Station: ST-44
Torque (Nm): 8
Cycle time (s): 252

Step 1: Visual check

Step 2: Torque to specification

Step 3: Visual check

Step 4: Torque to specification

Step 5: Clean mating surface

Step 6: Record result

Step 7: Torque to specification