WORK INSTRUCTION

Document ID: DOC-0000370
Project: PRJ-033
Uploaded on: 2023-04-27
Uploaded by: user006
Export class: EAR99

Assembly of P-100490 at plant PLT01

Part Number: P-100490
Revision: A.1
Plant: PLT01
Station: ST-84
Torque (Nm): 5
Cycle time (s): 59

Step 1: Visual check

Step 2: Apply thread locker

Step 3: Clean mating surface

Step 4: Torque to specification

Step 5: Inspect incoming part

Step 6: Move to next station

Step 7: Visual check