WORK INSTRUCTION

Document ID: DOC-0000386
Project: PRJ-040
Uploaded on: 2023-05-03
Uploaded by: user190
Export class: EAR99

Assembly of P-100199 at plant PLT03

Part Number: P-100199
Revision: A.1
Plant: PLT03
Station: ST-97
Torque (Nm): 12
Cycle time (s): 284

Step 1: Torque to specification

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Fit fasteners

Step 5: Clean mating surface

Step 6: Clean mating surface

Step 7: Record result

Assembly of P-100512 at plant PLT01

Part Number: P-100512
Revision: A.1
Plant: PLT01
Station: ST-59
Torque (Nm): 8
Cycle time (s): 259

Step 1: Record result

Step 2: Visual check

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Move to next station

Assembly of P-100264 at plant PLT04

Part Number: P-100264
Revision: A.1
Plant: PLT04
Station: ST-53
Torque (Nm): 5
Cycle time (s): 258

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Record result

Step 6: Clean mating surface