WORK INSTRUCTION

Document ID: DOC-0002656
Project: PRJ-024
Uploaded on: 2026-04-17
Uploaded by: user102
Export class: EAR99

Assembly of P-100562 at plant PLT04

Part Number: P-100562
Revision: A.1
Plant: PLT04
Station: ST-61
Torque (Nm): 5
Cycle time (s): 300

Step 1: Visual check

Step 2: Record result

Step 3: Record result

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Apply thread locker

Step 7: Apply thread locker

Assembly of P-100277 at plant PLT04

Part Number: P-100277
Revision: B.1
Plant: PLT04
Station: ST-84
Torque (Nm): 5
Cycle time (s): 163

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Fit fasteners

Step 4: Torque to specification

Step 5: Fit fasteners