WORK INSTRUCTION

Document ID: DOC-0002986
Project: PRJ-011
Uploaded on: 2026-09-29
Uploaded by: user171
Export class: EAR99

Assembly of P-104251 at plant PLT01

Part Number: P-104251
Revision: A.1
Plant: PLT01
Station: ST-11
Torque (Nm): 8
Cycle time (s): 133

Step 1: Torque to specification

Step 2: Apply thread locker

Step 3: Clean mating surface

Step 4: Apply thread locker

Step 5: Clean mating surface

Step 6: Inspect incoming part

Step 7: Apply thread locker

Step 8: Visual check