WORK INSTRUCTION

Document ID: DOC-0000601
Project: PRJ-002
Uploaded on: 2023-08-14
Uploaded by: user119
Export class: EAR99

Assembly of P-100414 at plant PLT01

Part Number: P-100414
Revision: A.1
Plant: PLT01
Station: ST-60
Torque (Nm): 8
Cycle time (s): 133

Step 1: Apply thread locker

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Record result

Step 7: Inspect incoming part