WORK INSTRUCTION

Document ID: DOC-0001391
Project: PRJ-034
Uploaded on: 2024-09-02
Uploaded by: user065
Export class: EAR99

Assembly of P-101832 at plant PLT02

Part Number: P-101832
Revision: A.1
Plant: PLT02
Station: ST-27
Torque (Nm): 12
Cycle time (s): 69

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Fit fasteners

Step 4: Visual check

Step 5: Clean mating surface