# WORK INSTRUCTION

**Document ID:** DOC-0001398
**Project:** PRJ-017
**Uploaded on:** 2024-09-05
**Uploaded by:** user158
**Export class:** EAR99

## Assembly of P-100935 at plant PLT01

**Part Number:** P-100935
**Revision:** A.1
**Plant:** PLT01
**Station:** ST-61
**Torque (Nm):** 12
**Cycle time (s):** 78

Step 1: Torque to specification

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Visual check

Step 5: Torque to specification

Step 6: Apply thread locker

Step 7: Fit fasteners

Step 8: Move to next station

## Assembly of P-100248 at plant PLT01

**Part Number:** P-100248
**Revision:** B.1
**Plant:** PLT01
**Station:** ST-41
**Torque (Nm):** 20
**Cycle time (s):** 63

Step 1: Fit fasteners

Step 2: Visual check

Step 3: Clean mating surface

Step 4: Apply thread locker

Step 5: Visual check

Step 6: Record result

Step 7: Apply thread locker