EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0001716
Project: PRJ-003
Uploaded on: 2025-01-31
Uploaded by: user181
Export class: ECCN-3A001

Assembly of P-101641 at plant PLT03

Part Number: P-101641
Revision: A.1
Plant: PLT03
Station: ST-76
Torque (Nm): 8
Cycle time (s): 142

Step 1: Visual check

Step 2: Record result

Step 3: Clean mating surface

Step 4: Apply thread locker

Step 5: Fit fasteners

Step 6: Apply thread locker