WORK INSTRUCTION

Document ID: DOC-0003037
Project: PRJ-034
Uploaded on: 2026-10-25
Uploaded by: user187
Export class: EAR99

Assembly of P-100469 at plant PLT03

Part Number: P-100469
Revision: A.1
Plant: PLT03
Station: ST-18
Torque (Nm): 2.5
Cycle time (s): 284

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Clean mating surface

Step 4: Clean mating surface

Step 5: Inspect incoming part