WORK INSTRUCTION

Document ID: DOC-0003046
Project: PRJ-014
Uploaded on: 2026-10-27
Uploaded by: user195
Export class: EAR99

Assembly of P-100430 at plant PLT01

Part Number: P-100430
Revision: B.1
Plant: PLT01
Station: ST-54
Torque (Nm): 2.5
Cycle time (s): 164

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Record result

Step 5: Visual check

Step 6: Apply thread locker

Step 7: Clean mating surface

Step 8: Record result