WORK INSTRUCTION

Document ID: DOC-0003053
Project: PRJ-008
Uploaded on: 2026-10-31
Uploaded by: user035
Export class: EAR99

Assembly of P-104400 at plant PLT02

Part Number: P-104400
Revision: A.1
Plant: PLT02
Station: ST-67
Torque (Nm): 12
Cycle time (s): 291

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Fit fasteners

Step 4: Fit fasteners

Step 5: Fit fasteners

Step 6: Visual check

Step 7: Inspect incoming part

Step 8: Move to next station

Assembly of P-102509 at plant PLT03

Part Number: P-102509
Revision: A.1
Plant: PLT03
Station: ST-91
Torque (Nm): 2.5
Cycle time (s): 188

Step 1: Inspect incoming part

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Inspect incoming part

Step 5: Clean mating surface

Assembly of P-103872 at plant PLT03

Part Number: P-103872
Revision: A.1
Plant: PLT03
Station: ST-90
Torque (Nm): 20
Cycle time (s): 56

Step 1: Inspect incoming part

Step 2: Move to next station

Step 3: Visual check

Step 4: Torque to specification

Step 5: Fit fasteners

Step 6: Visual check