WORK INSTRUCTION

Document ID: DOC-0000486
Project: PRJ-013
Uploaded on: 2023-06-20
Uploaded by: user092
Export class: EAR99

Assembly of P-100523 at plant PLT04

Part Number: P-100523
Revision: A.1
Plant: PLT04
Station: ST-35
Torque (Nm): 5
Cycle time (s): 287

Step 1: Visual check

Step 2: Record result

Step 3: Visual check

Step 4: Visual check

Step 5: Move to next station

Step 6: Fit fasteners

Assembly of P-100633 at plant PLT02

Part Number: P-100633
Revision: A.1
Plant: PLT02
Station: ST-62
Torque (Nm): 20
Cycle time (s): 160

Step 1: Clean mating surface

Step 2: Move to next station

Step 3: Record result

Step 4: Move to next station

Step 5: Fit fasteners

Step 6: Fit fasteners