WORK INSTRUCTION

Document ID: DOC-0000492
Project: PRJ-018
Uploaded on: 2023-06-21
Uploaded by: user186
Export class: EAR99

Assembly of P-100482 at plant PLT01

Part Number: P-100482
Revision: A.1
Plant: PLT01
Station: ST-23
Torque (Nm): 2.5
Cycle time (s): 225

Step 1: Visual check

Step 2: Clean mating surface

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Fit fasteners

Step 6: Clean mating surface

Step 7: Fit fasteners

Step 8: Inspect incoming part