EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0000502
Project: PRJ-040
Uploaded on: 2023-06-27
Uploaded by: user191
Export class: ECCN-3A001

Assembly of P-100776 at plant PLT03

Part Number: P-100776
Revision: A.1
Plant: PLT03
Station: ST-30
Torque (Nm): 5
Cycle time (s): 257

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Visual check

Step 6: Fit fasteners

Step 7: Move to next station

Step 8: Inspect incoming part

Assembly of P-100166 at plant PLT04

Part Number: P-100166
Revision: B.1
Plant: PLT04
Station: ST-20
Torque (Nm): 12
Cycle time (s): 131

Step 1: Move to next station

Step 2: Visual check

Step 3: Torque to specification

Step 4: Record result

Step 5: Inspect incoming part

Step 6: Visual check