WORK INSTRUCTION

Document ID: DOC-0000504
Project: PRJ-006
Uploaded on: 2023-06-27
Uploaded by: user055
Export class: EAR99

Assembly of P-100529 at plant PLT03

Part Number: P-100529
Revision: A.1
Plant: PLT03
Station: ST-83
Torque (Nm): 12
Cycle time (s): 214

Step 1: Visual check

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Torque to specification

Step 5: Torque to specification

Step 6: Move to next station

Step 7: Torque to specification

Step 8: Record result

Assembly of P-100453 at plant PLT02

Part Number: P-100453
Revision: A.1
Plant: PLT02
Station: ST-19
Torque (Nm): 12
Cycle time (s): 232

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Clean mating surface

Step 5: Torque to specification

Step 6: Visual check

Assembly of P-100785 at plant PLT02

Part Number: P-100785
Revision: A.1
Plant: PLT02
Station: ST-12
Torque (Nm): 8

Cycle time (s): 227

Step 1: Inspect incoming part

Step 2: Record result

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Visual check

Step 6: Visual check

Step 7: Move to next station