WORK INSTRUCTION

Document ID: DOC-0000224
Project: PRJ-034
Uploaded on: 2023-02-19
Uploaded by: user007
Export class: EAR99

Assembly of P-100333 at plant PLT01

Part Number: P-100333
Revision: A.1
Plant: PLT01
Station: ST-87
Torque (Nm): 8
Cycle time (s): 194

Step 1: Inspect incoming part

Step 2: Fit fasteners

Step 3: Inspect incoming part

Step 4: Clean mating surface

Step 5: Inspect incoming part

Step 6: Record result

Step 7: Torque to specification