EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0002872
Project: PRJ-013
Uploaded on: 2026-07-31
Uploaded by: user158
Export class: ECCN-3A001

Assembly of P-100939 at plant PLT01

Part Number: P-100939
Revision: B.1
Plant: PLT01
Station: ST-46
Torque (Nm): 20
Cycle time (s): 134

Step 1: Fit fasteners

Step 2: Inspect incoming part

Step 3: Visual check

Step 4: Move to next station

Step 5: Torque to specification

Step 6: Inspect incoming part

Step 7: Move to next station