WORK INSTRUCTION

Document ID: DOC-0000242
Project: PRJ-021
Uploaded on: 2023-02-26
Uploaded by: user161
Export class: EAR99

Assembly of P-100175 at plant PLT04

Part Number: P-100175
Revision: A.1
Plant: PLT04
Station: ST-76
Torque (Nm): 8
Cycle time (s): 132

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Record result

Step 4: Record result

Step 5: Clean mating surface

Assembly of P-100271 at plant PLT04

Part Number: P-100271
Revision: A.1
Plant: PLT04
Station: ST-10
Torque (Nm): 12
Cycle time (s): 75

Step 1: Clean mating surface

Step 2: Record result

Step 3: Inspect incoming part

Step 4: Record result

Step 5: Record result

Step 6: Visual check

Step 7: Move to next station