WORK INSTRUCTION

Document ID: DOC-0000252
Project: PRJ-006
Uploaded on: 2023-03-03
Uploaded by: user095
Export class: EAR99

Assembly of P-100314 at plant PLT03

Part Number: P-100314
Revision: A.1
Plant: PLT03
Station: ST-33
Torque (Nm): 2.5
Cycle time (s): 279

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Fit fasteners

Step 4: Visual check

Step 5: Clean mating surface

Step 6: Record result

Step 7: Visual check