WORK INSTRUCTION

Document ID: DOC-0000280
Project: PRJ-019
Uploaded on: 2023-03-19
Uploaded by: user006
Export class: EAR99

Assembly of P-100259 at plant PLT04

Part Number: P-100259
Revision: A.1
Plant: PLT04
Station: ST-82
Torque (Nm): 2.5
Cycle time (s): 86

Step 1: Clean mating surface

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Torque to specification

Step 5: Move to next station