WORK INSTRUCTION

Document ID: DOC-0001659
Project: PRJ-007
Uploaded on: 2025-01-04
Uploaded by: user011
Export class: EAR99

Assembly of P-100360 at plant PLT04

Part Number: P-100360
Revision: B.1
Plant: PLT04
Station: ST-86
Torque (Nm): 20
Cycle time (s): 56

Step 1: Move to next station

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Visual check

Step 5: Inspect incoming part