WORK INSTRUCTION

Document ID: DOC-0001679
Project: PRJ-015
Uploaded on: 2025-01-12
Uploaded by: user125
Export class: EAR99

Assembly of P-101059 at plant PLT02

Part Number: P-101059
Revision: A.1
Plant: PLT02
Station: ST-44
Torque (Nm): 12
Cycle time (s): 124

Step 1: Torque to specification

Step 2: Record result

Step 3: Clean mating surface

Step 4: Torque to specification

Step 5: Visual check

Step 6: Clean mating surface

Step 7: Record result

Step 8: Visual check

Assembly of P-102497 at plant PLT04

Part Number: P-102497
Revision: A.1
Plant: PLT04
Station: ST-20
Torque (Nm): 5
Cycle time (s): 269

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Record result

Step 4: Torque to specification

Step 5: Fit fasteners