ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0001693
Project: PRJ-005
Uploaded on: 2025-01-20
Uploaded by: user171
Export class: ITAR-USML-XIX

Assembly of P-102651 at plant PLT03

Part Number: P-102651
Revision: A.1
Plant: PLT03
Station: ST-78
Torque (Nm): 12
Cycle time (s): 133

Step 1: Move to next station

Step 2: Inspect incoming part

Step 3: Fit fasteners

Step 4: Torque to specification

Step 5: Torque to specification

Step 6: Visual check

Step 7: Visual check

Assembly of P-100578 at plant PLT01

Part Number: P-100578
Revision: A.1
Plant: PLT01
Station: ST-40
Torque (Nm): 12
Cycle time (s): 108

Step 1: Visual check

Step 2: Record result

Step 3: Fit fasteners

Step 4: Visual check

Step 5: Visual check