EXPORT CONTROLLED - ECCN 3A001

WORK INSTRUCTION

Document ID: DOC-0002587
Project: PRJ-037
Uploaded on: 2026-03-13
Uploaded by: user062
Export class: ECCN-3A001

Assembly of P-102191 at plant PLT03

Part Number: P-102191
Revision: A.1
Plant: PLT03
Station: ST-12
Torque (Nm): 5
Cycle time (s): 90

Step 1: Torque to specification

Step 2: Move to next station

Step 3: Inspect incoming part

Step 4: Move to next station

Step 5: Inspect incoming part

Step 6: Record result