# WORK INSTRUCTION

**Document ID:** DOC-0001938
**Project:** PRJ-023
**Uploaded on:** 2025-05-16
**Uploaded by:** user029
**Export class:** EAR99

## Assembly of P-100310 at plant PLT01

**Part Number:** P-100310
**Revision:** B.1
**Plant:** PLT01
**Station:** ST-11
**Torque (Nm):** 8
**Cycle time (s):** 164

Step 1: Torque to specification

Step 2: Visual check

Step 3: Inspect incoming part

Step 4: Apply thread locker

Step 5: Move to next station

## Assembly of P-100186 at plant PLT01

**Part Number:** P-100186
**Revision:** A.1
**Plant:** PLT01
**Station:** ST-68
**Torque (Nm):** 12
**Cycle time (s):** 36

Step 1: Visual check

Step 2: Visual check

Step 3: Record result

Step 4: Inspect incoming part

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Torque to specification

## Assembly of P-101852 at plant PLT03

**Part Number:** P-101852
**Revision:** B.1
**Plant:** PLT03
**Station:** ST-66
**Torque (Nm):** 20
**Cycle time (s):** 72

Step 1: Torque to specification

Step 2: Record result

Step 3: Move to next station

Step 4: Apply thread locker

Step 5: Visual check