WORK INSTRUCTION

Document ID: DOC-0002953
Project: PRJ-030
Uploaded on: 2026-09-15
Uploaded by: user146
Export class: EAR99

Assembly of P-102835 at plant PLT04

Part Number: P-102835
Revision: A.1
Plant: PLT04
Station: ST-21
Torque (Nm): 20
Cycle time (s): 237

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Clean mating surface

Step 5: Inspect incoming part

Step 6: Clean mating surface

Step 7: Fit fasteners