WORK INSTRUCTION

Document ID: DOC-0001420
Project: PRJ-002
Uploaded on: 2024-09-14
Uploaded by: user168
Export class: EAR99

Assembly of P-100514 at plant PLT03

Part Number: P-100514
Revision: B.1
Plant: PLT03
Station: ST-84
Torque (Nm): 5
Cycle time (s): 177

Step 1: Torque to specification

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Inspect incoming part

Step 5: Record result

Step 6: Inspect incoming part

Step 7: Inspect incoming part

Step 8: Inspect incoming part

Assembly of P-100711 at plant PLT02

Part Number: P-100711
Revision: A.1
Plant: PLT02
Station: ST-28
Torque (Nm): 8
Cycle time (s): 102

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Visual check

Step 4: Fit fasteners

Step 5: Inspect incoming part

Step 6: Torque to specification