WORK INSTRUCTION

Document ID: DOC-0001451
Project: PRJ-002
Uploaded on: 2024-09-28
Uploaded by: user134
Export class: EAR99

Assembly of P-101278 at plant PLT01

Part Number: P-101278
Revision: A.1
Plant: PLT01
Station: ST-14
Torque (Nm): 8
Cycle time (s): 95

Step 1: Clean mating surface

Step 2: Fit fasteners

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Move to next station

Step 6: Visual check