WORK INSTRUCTION

Document ID: DOC-0000016
Project: PRJ-025
Uploaded on: 2022-11-11
Uploaded by: user115
Export class: EAR99

Assembly of P-100004 at plant PLT03

Part Number: P-100004
Revision: A.1
Plant: PLT03
Station: ST-16
Torque (Nm): 8
Cycle time (s): 151

Step 1: Move to next station

Step 2: Torque to specification

Step 3: Clean mating surface

Step 4: Visual check

Step 5: Record result