WORK INSTRUCTION

Document ID: DOC-0000020
Project: PRJ-006
Uploaded on: 2022-11-14
Uploaded by: user181
Export class: EAR99

Assembly of P-100033 at plant PLT01

Part Number: P-100033
Revision: A.1
Plant: PLT01
Station: ST-42
Torque (Nm): 8
Cycle time (s): 61

Step 1: Visual check

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Record result

Step 5: Torque to specification

Step 6: Torque to specification

Step 7: Apply thread locker

Assembly of P-100031 at plant PLT03

Part Number: P-100031
Revision: A.1
Plant: PLT03
Station: ST-75
Torque (Nm): 8
Cycle time (s): 35

Step 1: Visual check

Step 2: Visual check

Step 3: Record result

Step 4: Record result

Step 5: Torque to specification

Step 6: Record result

Step 7: Torque to specification