WORK INSTRUCTION

Document ID: DOC-0000033
Project: PRJ-027
Uploaded on: 2022-11-19
Uploaded by: user178
Export class: EAR99

Assembly of P-100060 at plant PLT01

Part Number: P-100060
Revision: A.1
Plant: PLT01
Station: ST-58
Torque (Nm): 12
Cycle time (s): 230

Step 1: Inspect incoming part

Step 2: Fit fasteners

Step 3: Clean mating surface

Step 4: Record result

Step 5: Clean mating surface

Step 6: Visual check