WORK INSTRUCTION

Document ID: DOC-0000082
Project: PRJ-035
Uploaded on: 2022-12-13
Uploaded by: user192
Export class: EAR99

Assembly of P-100119 at plant PLT02

Part Number: P-100119
Revision: A.1
Plant: PLT02
Station: ST-23
Torque (Nm): 5
Cycle time (s): 101

Step 1: Clean mating surface

Step 2: Torque to specification

Step 3: Apply thread locker

Step 4: Torque to specification

Step 5: Clean mating surface

Step 6: Clean mating surface

Step 7: Visual check