WORK INSTRUCTION

Document ID: DOC-0000100
Project: PRJ-003
Uploaded on: 2022-12-21
Uploaded by: user032
Export class: EAR99

Assembly of P-100079 at plant PLT01

Part Number: P-100079
Revision: A.1
Plant: PLT01
Station: ST-24
Torque (Nm): 12
Cycle time (s): 37

Step 1: Inspect incoming part

Step 2: Move to next station

Step 3: Record result

Step 4: Record result

Step 5: Apply thread locker

Step 6: Fit fasteners

Step 7: Torque to specification

Step 8: Record result