WORK INSTRUCTION

Document ID: DOC-0000133
Project: PRJ-028
Uploaded on: 2023-01-07
Uploaded by: user009
Export class: EAR99

Assembly of P-100162 at plant PLT02

Part Number: P-100162
Revision: A.1
Plant: PLT02
Station: ST-21
Torque (Nm): 2.5
Cycle time (s): 203

Step 1: Visual check

Step 2: Inspect incoming part

Step 3: Move to next station

Step 4: Record result

Step 5: Visual check

Step 6: Visual check

Step 7: Apply thread locker

Assembly of P-100124 at plant PLT03

Part Number: P-100124
Revision: A.1
Plant: PLT03
Station: ST-56
Torque (Nm): 12
Cycle time (s): 203

Step 1: Visual check

Step 2: Record result

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Record result