WORK INSTRUCTION

Document ID: DOC-0000171
Project: PRJ-038
Uploaded on: 2023-01-23
Uploaded by: user127
Export class: EAR99

Assembly of P-100166 at plant PLT04

Part Number: P-100166
Revision: A.1
Plant: PLT04
Station: ST-59
Torque (Nm): 8
Cycle time (s): 294

Step 1: Move to next station

Step 2: Fit fasteners

Step 3: Record result

Step 4: Inspect incoming part

Step 5: Inspect incoming part

Step 6: Fit fasteners

Step 7: Fit fasteners

Step 8: Inspect incoming part

Assembly of P-100203 at plant PLT01

Part Number: P-100203
Revision: A.1
Plant: PLT01
Station: ST-76
Torque (Nm): 8
Cycle time (s): 30

Step 1: Inspect incoming part

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Move to next station

Step 5: Inspect incoming part

Step 6: Record result