WORK INSTRUCTION

Document ID: DOC-0000178
Project: PRJ-015
Uploaded on: 2023-01-28
Uploaded by: user039
Export class: EAR99

Assembly of P-100135 at plant PLT01

Part Number: P-100135
Revision: A.1
Plant: PLT01
Station: ST-61
Torque (Nm): 8
Cycle time (s): 184

Step 1: Clean mating surface

Step 2: Inspect incoming part

Step 3: Torque to specification

Step 4: Visual check

Step 5: Record result