WORK INSTRUCTION

Document ID: DOC-0000181
Project: PRJ-024
Uploaded on: 2023-01-30
Uploaded by: user096
Export class: EAR99

Assembly of P-100186 at plant PLT01

Part Number: P-100186
Revision: A.1
Plant: PLT01
Station: ST-38
Torque (Nm): 5
Cycle time (s): 183

Step 1: Inspect incoming part

Step 2: Clean mating surface

Step 3: Clean mating surface

Step 4: Clean mating surface

Step 5: Move to next station