ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0000195
Project: PRJ-039
Uploaded on: 2023-02-08
Uploaded by: user127
Export class: ITAR-USML-XIX

Assembly of P-100080 at plant PLT01

Part Number: P-100080
Revision: B.1
Plant: PLT01
Station: ST-89
Torque (Nm): 2.5
Cycle time (s): 261

Step 1: Fit fasteners

Step 2: Move to next station

Step 3: Torque to specification

Step 4: Fit fasteners

Step 5: Apply thread locker

Step 6: Record result

Step 7: Clean mating surface

Step 8: Torque to specification

Assembly of P-100022 at plant PLT03

Part Number: P-100022
Revision: A.1
Plant: PLT03
Station: ST-47
Torque (Nm): 2.5
Cycle time (s): 201

Step 1: Fit fasteners

Step 2: Torque to specification

Step 3: Move to next station

Step 4: Record result

Step 5: Move to next station

Step 6: Inspect incoming part

Step 7: Apply thread locker