WORK INSTRUCTION

Document ID: DOC-0000237
Project: PRJ-006
Uploaded on: 2023-02-24
Uploaded by: user138
Export class: EAR99

Assembly of P-100057 at plant PLT02

Part Number: P-100057
Revision: A.1
Plant: PLT02
Station: ST-80
Torque (Nm): 20
Cycle time (s): 273

Step 1: Fit fasteners

Step 2: Record result

Step 3: Apply thread locker

Step 4: Apply thread locker

Step 5: Torque to specification