ITAR CONTROLLED - USML CATEGORY XIX

WORK INSTRUCTION

Document ID: DOC-0000270
Project: PRJ-039
Uploaded on: 2023-03-14
Uploaded by: user111
Export class: ITAR-USML-XIX

Assembly of P-100402 at plant PLT02

Part Number: P-100402
Revision: A.1
Plant: PLT02
Station: ST-66
Torque (Nm): 8
Cycle time (s): 43

Step 1: Inspect incoming part

Step 2: Torque to specification

Step 3: Torque to specification

Step 4: Visual check

Step 5: Clean mating surface

Step 6: Torque to specification

Step 7: Visual check

Step 8: Move to next station

Assembly of P-100080 at plant PLT01

Part Number: P-100080
Revision: B.1
Plant: PLT01
Station: ST-99
Torque (Nm): 5
Cycle time (s): 186

Step 1: Record result

Step 2: Inspect incoming part

Step 3: Fit fasteners

Step 4: Inspect incoming part

Step 5: Torque to specification

Step 6: Inspect incoming part

Step 7: Inspect incoming part

Step 8: Visual check

Assembly of P-100169 at plant PLT01

Part Number: P-100169

Revision:	A.1
Plant:	PLT01
Station:	ST-45
Torque (Nm):	2.5
Cycle time (s):	178

Step 1: Torque to specification

Step 2: Torque to specification

Step 3: Inspect incoming part

Step 4: Fit fasteners

Step 5: Torque to specification