WORK INSTRUCTION

Document ID: DOC-0000348
Project: PRJ-022
Uploaded on: 2023-04-16
Uploaded by: user191
Export class: EAR99

Assembly of P-100161 at plant PLT02

Part Number: P-100161
Revision: A.1
Plant: PLT02
Station: ST-11
Torque (Nm): 8
Cycle time (s): 257

Step 1: Fit fasteners

Step 2: Visual check

Step 3: Move to next station

Step 4: Visual check

Step 5: Torque to specification