WORK INSTRUCTION

Document ID: DOC-0000487
Project: PRJ-021
Uploaded on: 2023-06-20
Uploaded by: user195
Export class: EAR99

Assembly of P-100031 at plant PLT03

Part Number: P-100031
Revision: C.1
Plant: PLT03
Station: ST-42
Torque (Nm): 2.5
Cycle time (s): 198

Step 1: Fit fasteners

Step 2: Torque to specification

Step 3: Clean mating surface

Step 4: Fit fasteners

Step 5: Visual check