WORK INSTRUCTION

Document ID: DOC-0000533
Project: PRJ-013
Uploaded on: 2023-07-12
Uploaded by: user049
Export class: EAR99

Assembly of P-100064 at plant PLT04

Part Number: P-100064
Revision: A.1
Plant: PLT04
Station: ST-96
Torque (Nm): 12
Cycle time (s): 89

Step 1: Torque to specification

Step 2: Clean mating surface

Step 3: Move to next station

Step 4: Fit fasteners

Step 5: Torque to specification

Step 6: Torque to specification